

SERVICE EXCHANGE PRODUCT ADVISORY

DATE:	October 7, 2008
DISTRIBUTION:	All Customers ~ Maintenance Departments
FROM :	Dante Frescura ~ IFI Exchange Service Manager E-mail: dfrescura@ificanada.com Phone#: (705) 523-1621
C.C.:	IFI Product & Account Managers, IFI Field Service Technicians, Peter Villgren, Daryl Rautiainen, Jay Michaud, Barrie Therrien, Peter Tario
SUBJECT :	SERVICE EXCHANGE AXLE
IFI PART# :	IFI03000EXCH
APPLICABLE UNITS :	6000 SERIES MINECAT 100

At Industrial Fabrication we have new or reconditioned service exchange components for your MINECAT utility vehicle. We can offer repair and return or modified exchange axles. To ensure quality assurance, we pressure test the park brake, service brake and wheel end seals. Our main objective is to lower your operating costs and increase the availability of your fleet of IFI utility vehicles.



All components and kits are created from genuine OEM parts that you can depend on for quality and proper fit. Using the right component or kit will ensure that all required parts are available when you need it.

***For futher information please contact the IFI Service Department at
(705) 523-1621 or e-mail service@ificanada.com***